

## State Water Resources Control Board

January 31, 2018

(Via email and Certified Mail)  
**CERTIFIED MAIL**  
**NO. 7016 3010 0000 5907 1585**

Mr. Mike Johnson  
Senior Plumber  
North County Regional Center  
325 South Melrose Drive  
Vista, California 92083  
[mike.johnson@sdcounty.ca.gov](mailto:mike.johnson@sdcounty.ca.gov)

**SUBJECT: RETURN TO COMPLIANCE; UNDERGROUND STORAGE TANK SYSTEMS AT  
NORTH COUNTY REGIONAL CENTER, 325 SOUTH MELROSE DRIVE, VISTA**

Dear Mr. Johnson:

The State Water Resources Control Board is in receipt of documents you submitted in response to our November 30, 2017 Notice of Violation (NOV). The documents demonstrate that the ongoing violations cited in the NOV were corrected. Thank you for your cooperation.

Sincerely,



Amantha Henkel  
Senior Environmental Scientist  
UST Enforcement Unit  
**Office of Enforcement**

cc: (via email only)

Ms. Maryam Dorsey, Chief  
Hazardous Material Division  
County of San Diego Department of  
Environmental Health  
[maryam.dorsey@sdcounty.ca.gov](mailto:maryam.dorsey@sdcounty.ca.gov)

Mr. Robert Rapista  
Supervising Environmental Health Specialist  
Underground Storage Tank Program  
County of San Diego Department of  
Environmental Health  
[robert.rapista@sdcounty.ca.gov](mailto:robert.rapista@sdcounty.ca.gov)